

MATERIAL SUPLEMENTAR 1: Séries temporais de imagens registradas no CoastSnap em Conde-PB

Aplicação CoastSnap para proposta de monitoramento cidadão em ecossistemas costeiros-marinhos no domínio da Mata Atlântica: caso no município do Conde – Paraíba

Stephani Somekawa, Ismerina C. L. de Oliveira, Leticia das N. Felix, Marcia Maria A. de Sousa, Rosiete M. da Silva, Tânia C. Dantas, Maristela D. de Queiroz, Luana C. C. Silva, Yedda C. B. B. Oliveira, Camila C. P. de Brito, Viviana M. Velásquez, Francisco Araos, Luciana S. Esteves, Bráulio Almeida Santos, Allan Yu Iwama

PRAIA DO AMOR

O local escolhido para registro das imagens através do aplicativo é no Restaurante Cantinho do Amor, localizado na entrada principal da praia, por ser um local alto, de fácil acesso, com bom ângulo de visada da faixa de areia e por ser uma possível parceria para a estação fixa de monitoramento onde podem se tornar “guardiões” da estação. A sugestão do local foi feita pelas voluntárias que nos comunicaram sobre a

fragilidade das falésias presentes na praia que sofrem com a erosão causada principalmente pela variação das marés.

A Figura 1, demonstra uma série temporal na praia do Amor, a partir dessa linha do tempo foi possível analisar essas mudanças ao longo dos meses do projeto.

Uma mudança interessante que se pode analisar foi em relação a erosão da linha de praia, do dia 09/12 ao dia 16/12 devido às ações das ondas em maré alta



FIGURA 1: Linha do tempo da Praia do Amor, imagens capturadas de setembro a dezembro de 2022. Autodescrição: sequência de fotografias de uma praia (chamada Praia do Amor)

houve a formação de uma escarpa praial, como um “degrau”, esse tipo de feição ocorre com frequência nessa praia, o interessante seria uma quantidade maior de fotos ao longo do tempo para acompanhar os avanços da formação dessas escarpas.

Uma cavidade formada na falésia no final dessa porção da praia chama atenção, essa erosão é causada pela alta maré que atinge a falésia erodindo e formando um buraco nessa feição. Relatos de moradores locais nos informaram que essa ponta da falésia era maior em sentido para o mar e que outra cavidade já havia sido formada anos atrás e com o tempo foi

totalmente erodida e agora esta seria uma nova cavidade que está aumentando gradativamente. Esse é um ponto muito relevante que pode ser observado ao longo do tempo pelo app CoastSnap, no período de desenvolvimento deste projeto (6 meses) não foi possível observar uma mudança perceptível nesta cavidade, mas se observarmos uma fotografia registrada e publicada pelo restaurante Cantinho do Amor nas redes sociais em 2019 na Figura 2, podemos observar que houve mudanças na abertura dessa cavidade em relação a dezembro de 2022 (Figura 3), num período de aproximadamente 4 anos.



FIGURA2: Praia do amor em 2019, com destaque para cavidade na ponta da falésia. Fonte: Cantinho do Amor (Facebook). Disponível em: <https://www.facebook.com/photo/?fbid=1647812958698925&set=pb.100039534506013.-2207520000>. Acesso em : 25/01/2023. Autodescrição: foto faixa de areia de praia com sinalização de erosão costeira.




FIGURA 3: Praia do amor em 2022, destaque para abertura da cavidade na ponta da falésia. A) Foto tirada pelo app CoastSnap durante uma ação de monitoramento. B) Foto próxima da cavidade, observa-se proximidade com a linha da costa. Autodescrição: foto faixa de areia de praia com sinalização de erosão costeira.

PRAIA DE JACUMÃ

A praia de Jacumã é uma praia central do Conde, possui um maior número de visitas em relação às outras praias do Conde, possui calçadão, ciclovia, quiosques e uma praça com quadra e pista de skate inauguradas em 2018.

O ponto de observação localiza-se na praça do mar com vista para a praia de Carapibus ao fundo (Figura 4). Essa praia possui uma contenção de

concreto que barra a maré e impede o mar de chegar na área da praça (Figura 5). No fundo da imagem à esquerda há a presença de um afloramento de rocha calcária (*beachrocks*) da Formação Maria Farinha, este afloramento é totalmente encoberto na maré alta como observado na figura 4, no dia 16/12/2022, segundo as cientistas cidadãs, essa área ocorre deslizamento das falésias, isso se deve ao fato de serem dunas ativas e devido a ocupação humana muito próxima de sua margem (Fig.4).



FIGURA 4: Fotos da praia de Jacumã tiradas na praça do mar. Ao fundo fica a praia de Carapibus. Autodescrição: foto faixa de areia de praia e variação da linha de maré.



FIGURA 5: Imagens aéreas (drone) da praia de Jacumã e Carapibus. A) Praia de Jacumã, praça do mar à esquerda 1- contenção de concreto; B) Praia de Carapibus 1- Ocupação humana nas margens da falésia, 2 e 3 - afloramento calcário (*beachrocks*). Autodescrição: fotos aéreas de praias sinalizando erosão costeira

PRAIA DE TABATINGA II

A praia de Tabatinga II possui dois pontos de observação, na entrada central da praia ao lado esquerdo da escada de madeira sentido norte e do lado direito da escada sentido sul.

A escolha desse ponto é devido a fragilidade e susceptibilidade de feições geológicas que ocorrem na praia e às alterações da faixa de areia que ocorrem no local em tão pouco tempo. Além disso, o local possui um alto valor científico devido a sua formação geológica. Segundo Furrier (2007) na praia de Tabatinga

é possível observar terraços marinhos pleistocênicos e paleodunas. Esses terraços foram formados quando o nível relativo do mar esteve acima do atual, em 8 ± 2 metros, denominado de Transgressão Cananéia, que ocorreu por volta de 120.000 A.P. - Antes do Presente (Suguio e Martin, 1978). Este terraço pode ser classificado como frágil por ser de origem sedimentar e vulnerável por estar em um local onde sofre constante erosão tanto por causas naturais quanto causas antrópicas. A escada que aparece nas imagens da Figura 6, foi construída no próprio terraço e uma cavidade se formou na parte inferior por conta da alta maré.



FIGURA 6: Detalhes da praia de Tabatinga II. A) Erosão por ação antrópica, com a construção de uma escada na própria rocha e por causa natural, formando uma cavidade na parte inferior do terraço; B) Foto aérea do terraço de frente 1- detalhe para erosão que se forma cavidades na parte inferior do terraço e a livre circulação de pessoas na superfície; C) Foto aérea da praia 1- falésias ativas, 2- afloramento de rocha calcária, 3- ponto de observação, 4- ocupação humana sobre o terraço, muito próxima da escarpa. Autodescrição: fotos aéreas de praias sinalizando erosão costeira.

Do lado esquerdo da praia, sentido norte (Figura 7), observa-se o canal de maré que interliga o rio com o mar e que, em determinados períodos, ele se fecha formando um maceió, um tipo de formação típico da região, que ocorre normalmente em rios de pequeno porte com nascentes em platôs costeiros sedimentares e possui caudal suficiente na maré baixa para alcançar a barra da foz com o mar, gerando uma zona intermediária lacustre temporária. O monitoramento dessas mudanças é interessante para

saber o tipo de interação que ocorre nesse ambiente e entender quais as dinâmicas que fazem com que esse canal mude as direções de sua vazão. Pode-se observar que na foto do dia 21/10, 18/11 e 25/11 o canal está com sua vazão lateral, rente ao terraço marinho, já no dia 16/12 a vazão do canal muda a direção e formam-se escarpas o que indica um forte fluxo de água que erodiu essa área.

A face sul da praia (Figura 8), é possível observar parte do terraço marinho, no centro das imagens

há um afloramento de rocha calcária (*beachrock*) da Formação Maria Farinha (Furrier, 2007) e ao fundo falésias da outra porção da praia. Apesar de não haver

mudanças perceptíveis, além da variação da maré, essa área possui diversos elementos da paisagem importantes a serem monitorados.




FIGURA 7: Linha do tempo da praia de Tabatinga II face norte. Observam-se as mudanças de direção do canal de maré. Autodescrição: fotos de variação da linha da maré em praia.



FIGURA 8: Linha do tempo da praia de Tabatinga II, face sul. Observa-se parte do terraço marinho na parte inferior das imagens e no centro da imagem observam-se rochas calcárias da Formação Maria Farinha. Ao fundo das imagens parte das falésias ativas da outra porção da praia. Autodescrição: fotos de variação da linha da maré em praia

PRAIA DA ARAPUCA

O local de registro da praia da Arapuca é no mirante de Tambaba, esse ponto foi selecionado por já ser um local de grande visitação tanto turística, quanto dos moradores que frequentam a praia de Tambaba, também possui um quiosque que pode vir a ser uma parceria para a futura estação fixa.

A praia da Arapuca pertence a APA Tambaba, apesar de possuir baixa taxa de ocupação humana, a

praia recebe muitos visitantes para a prática de surfe sendo conhecida também como praia dos surfistas. Segundo as cientistas cidadãs, na maré alta o mar alcança a base das falésias impedindo a passagem.

Nas imagens da Figura 9, a praia não aparenta mudanças perceptíveis nos meses de monitoramento. Através das imagens aéreas feitas por drone pode-se observar uma voçoroca presente nessa praia que não dá para identificar pelas fotos capturadas pelo aplicativo.



FIGURA 9: Praia da Arapuca, não aparenta mudanças perceptíveis. Autodescrição: fotos paisagem de praia

REFERÊNCIAS

Furrier, M. (2007). *Caracterização geomorfológica e do meio físico da folha João Pessoa - 1: 100.000*. 2007. [Tese de Doutorado - Universidade de São Paulo]. <https://doi.org/10.11606/T.8.2007.tde-04062007-151800>

Suguio, K. & Martin, L. (1978). *Formações quater-*

nárias marinhas do litoral paulista e sul fluminense | Quaternary marine formations of the state of São Paulo and southern Rio de Janeiro. The Brazilian National Working Group for the IGCP Project 61. <https://repositorio.usp.br/directbitstream/448a6dc7-c-1f8-4940-9392-74a7a59bde49/3076219.pdf>.

MATERIAL SUPLEMENTAR 2: Dados brutos coletados, analisados #CoastSnapCondePB

Dados de dados pode ser acessada pelo [link aqui](#)

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOTTED AT	CHANGES LAST UP-DATE	REA-SON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMAGE CAPTURE TYPE	TIDE LEVEL	DIV METHOD	PHOTO HEIGHT	SPOT NAME	DESCRIPTION	CREATED AT	MODIFIED AT	DELETED AT
658635	658635	-7275298	-34803580	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/6164967emf-qw6r19d6g3rv4frez.jpg	Praia do amor	8/5/22 9:25				FALSO				160			8/5/22 12:26		
658642	658642	-7274853	-34803323	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/62608524qz-jlxxv6yq4f04f1rz3ktsfx.jpg	Rest. Cantinho do amor test 1	8/5/22 9:50				FALSO				160			8/5/22 12:51		
658646	658646	-7274853	-34803323	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/62608524qz-jlxxv6yq4f04f1rz3ktsfx.jpg	Rest. canto do amor test 2	8/5/22 9:53				FALSO				160			8/5/22 12:54		
658647	658647	-7274853	-34803323	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/62608524qz-jlxxv6yq4f04f1rz3ktsfx.jpg	Rest. Canto do amor test3	8/5/22 9:55				FALSO				160			8/5/22 12:55		
658645	658635	-7275298	-34.80358	true	"Free Roaming"	https://files.spotteron.com/images/spots/000037/2022/08/05/62608524qz-jlxxv6yq4f04f1rz3ktsfx.jpg	"Praia do amor"	2022-08-05 09:55	"No Obvious Change"			true	"Snapshot (Standard)"	"Falling Tide"		160			"2022-08-05 12:53"		
658696	658635	-7275298	-34.80358	true	"Free Roaming"	https://files.spotteron.com/images/spots/000037/2022/08/07/6260944c-eh2mvh48za8434e22dlyxxax.jpg	"Praia do amor"	2022-08-05 09:56	"No Obvious Change"			false				160			"2022-08-07 10:28"		
658649	658635	-7275298	-34.80358	true	"Free Roaming"	https://files.spotteron.com/images/spots/000037/2022/08/05/640b67bc-px26xh4xhudiap5z9tkmkbox.jpg	"Praia do amor"	2022-08-05 09:59	"No Obvious Change"			true	"Snapshot (Standard)"	"Low Tide"		160			"2022-08-05 12:57"		
658662	658662	-7274807	-34803235	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/6164967emf-qw6r19d6g3rv4frez.jpg	Carapibus test 1	8/5/22 10:35				FALSO				160			8/5/22 13:36		
658664	658664	-7274807	-34803235	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/6164967emf-qw6r19d6g3rv4frez.jpg	Carapibus test 2	8/5/22 10:36				FALSO				160			8/5/22 13:37		
719640	https://www.spotteron.com/constsnapspots/719640	-7363.969		VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/11/18/98043xolm8aw1oyxkq5sk4d4e2zxr8k3.jpg	Mirante de Tambaba com vista para a praia da Arapuca	2022-08-05 12:04				FALSO				160			2022-11-18 18:44		no
658808	658808	-7293718	-34808424	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/636d456c-426d6w57150f9bha50df.jpg	Tabatinga 2 esquerda	8/5/22 14:30				FALSO				160			8/5/22 17:32		
658810	658810	-7293718	-34808424	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/704f9bvc-0227279d86d9d6195f2.jpg	Tabatinga 2 direita	8/5/22 14:32				FALSO				160			8/5/22 17:33		

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOT-TED AT	CHANGES LAST UP-DATE	REASON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMAGE CAPTURE TYPE	TIDE LEVEL	DIV METHOD	PHOTO HEIGHT	SPOT NAME	DESCRIPTION	CREATED AT	MODIFIED AT	DELETED
658806	658806	-7.313048	-34.802617	true	"Coastal Station"	https://files.spotteron.com/images/spots/000037/2022/08/05/gm3d4p29q65806g23kinkv30bzxxvmyt.jpg	"Tabatinga II"	2022-08-05 14:33				true	"Snapshot (Standard)"	"Low Tide"					"2022-08-05 17:31"		
658813	658813	-7.293718	-34.808424	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/oqnd7d4kbc7261resy3v4sq0v7f22xii2.jpg	Tabatinga 2	8/5/22 14:36				FALSO				160			8/5/22 17:36		
658815	658815	-7.293718	-34.808424	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/9enwxbie4ygcimbs3y1z9f0bxx3356.jpg	Tabatinga 2, Ternazo	8/5/22 14:37				FALSO				160			8/5/22 17:37		
658818	658818	-7.293718	-34.808424	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/11/18/v3gpaizcav4usm1kx927f73qesv7u.jpg	Tabatinga 2	8/5/22 14:42				FALSO				160			8/5/22 17:42		
719645	https://www.spotteron.com/coordinates/spots/719645	-7.312641	-34.802527	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/11/18/v3gpaizcav4usm1kx927f73qesv7u.jpg	Praia Tabatinga II - Norte	2022-08-05 14:43				FALSO				160			2022-11-18 19:02	2022-11-18 19:05	yes
719642	https://www.spotteron.com/coordinates/spots/719642	-7.312641	-34.802527	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/11/18/3k59sx39b6f0g20416dco614drolb.jpg	Praia Tabatinga II - Sul	2022-08-05 14:43				FALSO				160			2022-11-18 19:00		no
658820	658820	-7.312455	-34.803060	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/v5x6mhboc45xip0b7vzrbv9ppn9f0vq9.jpg	Tabatinga 2, Ternazo	8/5/22 14:48				FALSO				160			8/5/22 17:48		
658821	658821	-7.312455	-34.803060	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/08/05/zswaga7frecnlum7nazn029vnl2lq1le.jpg	Tabatinga 2, Ternazo	8/5/22 14:48				FALSO				160			8/5/22 17:49		
689222	689222	-7.276261	-34.800469	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/09/27/af03hb8kccdhves17cshhbx3bw7zpxpgl.jpg	Cantinho do amor	2022-09-27 07:10				VERDA-DEIRO	Snapshot (Standard)	Low Tide		0		Visão ampla da Costa, Presença de bambus e guarda-sol	2022-09-27 13:13		
689260	689260	-7.285817	-34.800544	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/09/27/af03hb8kccdhves17cshhbx3bw7zpxpgl.jpg	Ponta de Carapibus	2022-09-27 07:29				VERDA-DEIRO	Snapshot (Standard)	Low Tide		0		Praia de Carapibus com residências ponto do corpo de bombeiros - praia com alguns resíduos	2022-09-27 13:33		

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOTTED AT	CHANGES LAST UP. DATE	REASON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMAGE CAPTURE TYPE	TIDE LEVEL	DIV METHOD	PHOTO HEIGHT	SPOT NAME	DESCRIPTION	CREATED AT	MODIFIED AT	DELETED
689299	689299	-7.312.694	-34.802.581	VERDA-DEIRO	Free Rounding	https://files.spotteron.com/images/spots/000037/2022/09/27/5c30f4b2c974e1zfehdycy4blm7go.jpg	Tabatinga II - Sul	2022-09-27 08:12				VERDA-DEIRO	Snapshot (Standard)	Rising Tide		12		Presença de turistas a maré está subindo	2022-09-27 14:15		
689310	689310	-7.312.625	-34.802.567	VERDA-DEIRO	Free Rounding	https://files.spotteron.com/images/spots/000037/2022/09/27/1e07676c2e4e9b9d4d4dno8kx4z6v69.jpg	Tabatinga II - Norte	2022-09-27 08:12				VERDA-DEIRO	Snapshot (Standard)	Rising Tide		12		Encontro do mar com o Rio.	2022-09-27 14:17		
689344	689344	-7.364.003	-34.799.522	VERDA-DEIRO	Free Rounding	https://files.spotteron.com/images/spots/000037/2022/09/27/5c30f4b2c974e1zfehdycy4blm7go.jpg	Mirante de Tambaba	2022-09-27 08:43				VERDA-DEIRO	Snapshot (Standard)	Rising Tide			40	Vista para a praia de arapucas- praia linda	2022-09-27 14:44	2022-09-27 14:45	
704724	https://www.spotteron.com/constansp-spot-is/704724	-7.280.286	-34.800.891	VERDA-DEIRO	Coastmap Station	https://files.spotteron.com/images/spots/000037/2022/10/21/4d9b163b0c2px6hmet3n623b6cwp9sm6.jpg		2022-10-21 09:30				VERDA-DEIRO	Snapshot (Standard)	Low Tide					2022-10-21 12:35		no
704727	https://www.spotteron.com/constansp-spot-is/704727	-7.276.242	-34.800.509	VERDA-DEIRO	Coastmap Station	https://files.spotteron.com/images/spots/000037/2022/10/21/4d9b163b0c2px6hmet3n623b6cwp9sm6.jpg	Cantinho do amor	2022-10-21 10:00				VERDA-DEIRO	Snapshot (Standard)	Low Tide					2022-10-21 13:03		no
704736	https://www.spotteron.com/constansp-spot-is/704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/21/1f6a33b0c2gfhb6f6c6d4bf67f6z.jpg	Tabatinga 2	2022-10-21 10:25				VERDA-DEIRO	Snapshot (Standard)	Rising Tide					2022-10-21 13:27	2022-10-21 13:29	no
704736	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/21/1f6a33b0c2gfhb6f6c6d4bf67f6z.jpg	Tabatinga 2	2022-10-21 10:25				VERDA-DEIRO	Snapshot (Standard)	Rising Tide					2022-10-21 13:27		
704739	https://www.spotteron.com/constansp-spot-is/704739	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/21/1f6a33b0c2gfhb6f6c6d4bf67f6z.jpg	Tabatinga 2	2022-10-21 10:29	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Low Tide					2022-10-21 13:31		no
704739	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/21/1f6a33b0c2gfhb6f6c6d4bf67f6z.jpg	Tabatinga 2	2022-10-21 10:29	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Low Tide					2022-10-21 13:31		
704743	https://www.spotteron.com/constansp-spot-is/704743	-7.359.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/21/06c7475f6c3e20b6f6c2m2d086xy1.jpg	Tambaba	2022-10-21 10:51				VERDA-DEIRO	Snapshot (Standard)	Rising Tide	Tripod				2022-10-21 13:53	2022-10-21 13:54	no
704743	704743	-7.359.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/21/06c7475f6c3e20b6f6c2m2d086xy1.jpg	Tambaba	2022-10-21 10:51				VERDA-DEIRO	Snapshot (Standard)	Rising Tide	Tripod				2022-10-21 13:53		
708398	https://www.spotteron.com/constansp-spot-is/708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/8c9cwpv19nc9455g9t11pwr74hp31ic.jpg	Cantinho do amor	2022-10-28 08:11				VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Bar cantinho do amor		2022-10-28 11:14	2022-10-28 11:16	no

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOT-TED AT	CHANGES LAST UP-DATE	REA-SON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMAGE CAPTURE TYPE	TIDE LEVEL	DIV METHOD	PHOTO HEIGHT	SPOT NAME	DESCRIPTION	CREATED AT	MODIFIED AT	DELETED
708398	708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/66c9c94e19b529a55e9111e9c744p31e.jpg	Cantinho do amor	2022-10-28 08:11				VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Bar cantinho do amor		2022-10-28 11:14	2022-10-28 11:16	
708434	https://www.spotteron.com/constanapspots/708434	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/b6c9c94e19b529a55e9111e9c744p31e.jpg	Tabatinga 2	2022-10-28 08:35	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Próximo ao restaurante kuara			
708434	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/b6c9c94e19b529a55e9111e9c744p31e.jpg	Tabatinga 2	2022-10-28 08:35	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Próximo ao restaurante kuara, ao lado da escada.	2022-10-28 11:39		
708435	https://www.spotteron.com/constanapspots/708435	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/n1b1b0mme-v7h15auebhha4g83e4uk.jpg	Tabatinga 2	2022-10-28 08:40	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Lado direito da escada	2022-10-28 11:42		no
708435	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/n1b1b0mme-v7h15auebhha4g83e4uk.jpg	Tabatinga 2	2022-10-28 08:40	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Lado direito da escada	2022-10-28 11:42		
708444	https://www.spotteron.com/constanapspots/708444	-7.350.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/n1f5fvrte-gapanf9k42v4f3x4vxy.jpg	Tambaba	2022-10-28 08:54	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Mirante de tambaba	2022-10-28 11:57		no
708444	704743	-7.350.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/10/28/n1f5fvrte-gapanf9k42v4f3x4vxy.jpg	Tambaba	2022-10-28 08:54	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Mirante de tambaba	2022-10-28 11:57		
711582	https://www.spotteron.com/constanapspots/711582	-7.258.339	-34.806.893	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/04/5ybnhb-0z4z6kerrfij9z6dbabx2fkei.jpg	Cantinho do amor	2022-11-04 08:05				VERDA-DEIRO	Snapshot (Standard)	Low Tide	Tripod		Cantinho do amor	Não houve alteração perceptível	2022-11-04 11:11		no
711582	711582	-7.258.339	-34.806.893	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/04/5ybnhb-0z4z6kerrfij9z6dbabx2fkei.jpg	Cantinho do amor	2022-11-04 08:05				VERDA-DEIRO	Snapshot (Standard)	Low Tide	Tripod		Cantinho do amor	Não houve alteração perceptível	2022-11-04 11:11		
711596	https://www.spotteron.com/constanapspots/711596	-7.316.057	-34.804.397	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/04/4ym552fhe-mufemxy38p9k42v4f3x4vxy.jpg	Tabatinga 2	2022-11-04 08:35				VERDA-DEIRO	Snapshot (Standard)				Próximo ao restaurante kuara		2022-11-04 11:40		no
711598	https://www.spotteron.com/constanapspots/711598	-7.316.057	-34.804.397	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/04/4ym552fhe-mufemxy38p9k42v4f3x4vxy.jpg	Tabatinga 2	2022-11-04 08:41				VERDA-DEIRO	Snapshot (Standard)	Low Tide	Tripod		Lado direito da escada	Não houve alteração perceptível	2022-11-04 11:45		no
711602	https://www.spotteron.com/constanapspots/711602	-7.333.521	-34.809.883	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/04/xfbupx89q-fce81v2192umsk3irfb.jpg	Tambaba	2022-11-04 09:06				VERDA-DEIRO	Snapshot (Standard)	Low Tide	Tripod		Mirante tambaba		2022-11-04 12:09		no

ID	LINK	LATITUDE	LONGITUDE	CHE-CKBOX LO-CATION	CATE-GORY	IMAGE	NAME OF LOCATION	SPOT-TE- D AT	CHANGES_ LAST UP- DATE	REA-SON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMA-GE CAPTU- RE TYPE	TIDE LE- VEL	DIV_ ME- THOD	PHO- TO HEL- GHT	SPOT NAME	DESCRIP- TION	CREA- TED AT	MODI- FIED_ AT	DELE- TED	
716915	708398	-7.276.242	-34.800.442	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/eyxse03vnl-1300q0wvnr5kwe/65tssq.jpg	Cantinho do amor	2022-11-11 08:34	Coast Has Narrowed (Erosion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Rising Tide	Tripod		Bar cantinho do amor	Faixa estreita de areia	2022-11-11 11:44			
716916	https://www.spotteron.com/constanspots/716916	-7.258.339	-34.806.893	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/8nc33b6g-855u045452qzvr8hmv1q.jpg	Cantinho do amor	2022-11-11 08:37	Coast Has Narrowed (Erosion)	Tide												
716916	711582	-7.258.339	-34.806.893	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/8nc33b6g-855u045452qzvr8hmv1q.jpg	Cantinho do amor	2022-11-11 08:37	Coast Has Narrowed (Erosion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Rising Tide	Tripod		Cantinho do amor	Faixa de areia mais estreita	2022-11-11 11:44			
716927	https://www.spotteron.com/constanspots/716927	-7.276.242	-34.800.442	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/7780mvx877qspwxb414fdd-tb76w3f.jpg	Cantinho do amor	2022-11-11 08:45	Coast Has Narrowed (Erosion)	Tide		VERDA- DEIRO	Snapshot (Standard)	Rising Tide	Tripod		Bar cantinho do amor	Faixa de areia mais				
716927	708398	-7.276.242	-34.800.442	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/7780mvx877qspwxb414fdd-tb76w3f.jpg	Cantinho do amor	2022-11-11 08:45	Coast Has Narrowed (Erosion)	Tide		VERDA- DEIRO	Snapshot (Standard)	Rising Tide	Tripod		Bar cantinho do amor	Faixa de areia mais estreita	2022-11-11 11:57			
716980	https://www.spotteron.com/constanspots/716980	-7.316.057	-34.804.397	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/3m294v2-z709haxvnd0XKz849zb.jpg	Tabatinga 2	2022-11-11 09:42	Coast Has Grown (Accretion)	Tide												
716983	704736	-7.312.656	-34.802.545	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/3m294v2-z709haxvnd0XKz849zb.jpg	Tabatinga 2	2022-11-11 09:42	Coast Has Grown (Accretion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Rising Tide	Tripod			Não		2022-11-11 12:49	2022-11-11 12:50	
716991	https://www.spotteron.com/constanspots/716991	-7.312.656	-34.802.545	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/36zrdbkv-7zrtvxo07ozhahtr0djk7.jpg	Tabatinga 2 lado esquerdo da escada	2022-11-11 09:55	Coast Has Grown (Accretion)	Tide									Faixa de areia mais extensa fechando a abertura do maceiozinho com o mar	2022-11-11 13:00		
716996	https://www.spotteron.com/constanspots/716996	-7.333.521	-34.809.883	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/89vnx6f7n-81b9vcinfv0i3vz0q3w1.jpg	Tambaba	2022-11-11 10:20	Coast Has Narrowed (Erosion)	Tide												
719490	708398	-7.276.242	-34.800.442	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/11/11/89vnx6f7n-68uovmbv0s7vz0q3w1f0d9.jpg	Cantinho do amor	2022-11-18 08:14	Coast Has Grown (Accretion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Rising Tide	Tripod		Bar cantinho do amor	Mundica natural de acordo com o nível da maré	2022-11-18 11:23			

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOTTED AT	CHANGES LAST UP. DATE	REASON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMAGE CAPTURE TYPE	TIDE LEVEL	DIV METHOD	PHOTO HEIGHT	SPOT NAME	DESCRIPTION	CREATED AT	MODIFIED AT	DELETED
719496	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/00003720221118x38f28bue4962fink0kxsa71j860dfrs.jpg	Tabitiga 2 lado esquerdo da escada	2022-11-18 08:46	Coast Has Narrowed (Erosion)	Tide, Waves, Wind, Natural Trend		VERDA-DEIRO	Snapshot (Standard)	Rising Tide	Tripod			Faixa de areia mais estreita, dando mais proximidade do rio com o maior	2022-11-18 11:52		
721994	708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/00003720221125fub9p4rmluuhuprsk4kd7480pqs8pyk.jpg	Cantinho do amor	2022-11-25 08:11	Coast Has Narrowed (Erosion)	Tide, Waves, Natural Trend		VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Bar cantinho do amor	Faixa de areia mais estreita por conta da maré descendo	2022-11-25 11:15		
721998	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/00003720221125pdk4mzdfm0hoxs5fmmwbiogzms5vj.jpg	Tabitiga 2 lado esquerdo da escada	2022-11-25 08:39	Coast Has Narrowed (Erosion)	Tide, Natural Trend, Waves		VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Faixa de areia mais estreita, rio mais largo, presença de sargaçó(-vegetação marinha)	2022-11-25 11:43		
726992	708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/00003720221209gTrrkawc21q4ekzgagcs6l960bqde9xd.jpg	Cantinho do amor	2022-12-09 08:09	Coast Has Narrowed (Erosion)	Tide, Natural Trend		FALSO		Tripod			Bar cantinho do amor	Banco de areia formado pela maré alta	2022-12-09 11:28		
726992	708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/00003720221209gTrrkawc21q4ekzgagcs6l960bqde9xd.jpg	Cantinho do amor	2022-12-09 08:09	Coast Has Narrowed (Erosion)	Tide, Natural Trend		FALSO		Tripod			Bar cantinho do amor	Banco de areia formado pela maré alta	2022-12-09 11:28		
726992	https://www.spotteron.com/constant-spots/726992	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/00003720221209gTrrkawc21q4ekzgagcs6l960bqde9xd.jpg	Cantinho do amor	2022-12-09 08:09	Coast Has Narrowed (Erosion)	Tide											
726991	708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/00003720221209gTrrkawc21q4ekzgagcs6l960bqde9xd.jpg	Cantinho do amor	2022-12-09 08:13	Coast Has Narrowed (Erosion)	Tide, Waves, Natural Trend		VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Bar cantinho do amor	Faixa de areia mais estreita em função da maré baixando, deslizando de barrreira visível devido a erosão	2022-12-09 11:26		

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOT- TED_AT	CHANGES_ LAST UP- DATE	REA- SON_ FOR_ CHANGE	OTHER_ CAUSE	ADVANCED_ OPTIONS	IMA- GE CAPTU- RE_TYPE	TIDE LE- VEL	DIV_ ME- THOD	PHO- TO HEL- GHT	SPOT_ NAME	DESCRIP- TION	CREA- TED_AT	MODI- FIED_ AT	DELE- TED	
726991	708398	-7.276.242	-34.800.442	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/krn2m-z33yvgov30bmsisvov.jpg	Cantinho do amor	2022-12-09 08:13	Coast Has Narrowed (Erosion)	Tide, Waves, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Bar cantinho do amor	Faixa de areia mais estreita em função da maré baixando, deslizando de barrreira visível devido a erosão	2022-12-09 11:26			
726990	708398	-7.276.242	-34.800.442	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/jm2m-zf5w9mxcumxsf4mxt80q3ka.jpg	Cantinho do amor	2022-12-09 08:14	Coast Has Narrowed (Erosion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Bar cantinho do amor	Nenhuma mudança perceptível.	2022-12-09 11:21			
726990	708398	-7.276.242	-34.800.442	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/krn67h-zf5w9mxcumxsf4mxt80q3ka.jpg	Cantinho do amor	2022-12-09 08:14	Coast Has Narrowed (Erosion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Bar cantinho do amor	Nenhuma mudança perceptível.	2022-12-09 11:21			
727007	704736	-7.312.656	-34.802.545	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/n5tr67h-0f6d6cf3yef866p1xxpvtl.jpg	Tabatinga 2 lado esquerdo da escada	2022-12-09 09:13	Coast Has Grown (Accretion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Falling Tide	Tripod					2022-12-09 12:20		
727007	704736	-7.312.656	-34.802.545	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/n5tr67h-0f6d6cf3yef866p1xxpvtl.jpg	Tabatinga 2 lado esquerdo da escada	2022-12-09 09:13	Coast Has Grown (Accretion)	Tide, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Falling Tide	Tripod					2022-12-09 12:20		
727009	704736	-7.312.656	-34.802.545	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/r328558xyz-6bank6sfddoyfkz2fui.jpg	Tabatinga 2 lado esquerdo da escada	2022-12-09 09:14	Coast Has Grown (Accretion)	Tide, Waves, Wind, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Faixa de areia mais extensa fechando o encontro do Rio com o mar, presença de algas marinhas por tendência natural	2022-12-09 12:21			
727009	704736	-7.312.656	-34.802.545	VERDA- DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/r328558xyz-6bank6sfddoyfkz2fui.jpg	Tabatinga 2 lado esquerdo da escada	2022-12-09 09:14	Coast Has Grown (Accretion)	Tide, Waves, Wind, Natural Trend		VERDA- DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Faixa de areia mais extensa fechando o encontro do Rio com o mar, presença de algas marinhas por tendência natural	2022-12-09 12:21			

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOT-TED AT	CHANGES LAST UP-DATE	REA-SON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMAGE CAPTURE TYPE	TIDE LEVEL	DIV-METHOD	PHOTO HEIGHT	SPOT NAME	DESCRIPTION	CREATED AT	MODIFIED AT	DELETED
727011	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/psd0014de-49mLux7m0mV14593723k.jpg	Tabitiga 2 lado esquerdo da escada	2022-12-09 09:21	No Obvious Change			FALSO			Tripod			Maré baixa, presença de acúmulo de algas na areia	2022-12-09 12:23		
727011	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/psd0014de-49mLux7m0mV14593723k.jpg	Tabitiga 2 lado esquerdo da escada	2022-12-09 09:21	No Obvious Change			FALSO			Tripod			Maré baixa, presença de acúmulo de algas na areia	2022-12-09 12:23		
727011	https://www.spoteron.com/constmapspots/727011	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/psd0014de-49mLux7m0mV14593723k.jpg	Tabitiga 2 lado esquerdo da escada	2022-12-09 09:21	No Obvious Change			FALSO			Tripod			Maré baixa			
727012	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/02cy2ukc-g8lkzb085d11cuk45tzz.jpg	Tabitiga 2 lado esquerdo da escada	2022-12-09 09:25	Coast Has Grown (Accretion)	Tide, Natural Trend		FALSO			Tripod			Vazio do maciço fechado	2022-12-09 12:29		
727012	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/02cy2ukc-g8lkzb085d11cuk45tzz.jpg	Tabitiga 2 lado esquerdo da escada	2022-12-09 09:25	Coast Has Grown (Accretion)	Tide, Natural Trend		FALSO			Tripod			Vazio do maciço fechado	2022-12-09 12:29		
727012	https://www.spoteron.com/constmapspots/727012	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/rri5p1thmz-g8lkzb085d11cuk45tzz.jpg	Tabitiga 2 lado esquerdo da escada	2022-12-09 09:25	Coast Has Grown (Accretion)	Tide											
727027	704743	-7.359.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/rri5p1thmz-g8lkzb085d11cuk45tzz.jpg	Tambaba	2022-12-09 09:48	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod			Será que deu algum vazio ver como é que vai dar	2022-12-09 12:52		
727030	711602	-7.335.521	-34.809.883	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/m11f84psatqz-jf8q0g6d0m5m0mxb.jpg	Tambaba	2022-12-09 09:48	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Falling Tide	Tripod		Mirante tambaba	Nenhuma mudança perceptível	2022-12-09 12:56		
727031	704743	-7.359.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/ckem9cnv-gf8k0f8m84kpc5suw5k.jpg	Tambaba	2022-12-09 09:52	No Obvious Change			FALSO			Tripod			Maré baixa	2022-12-09 12:59		
727031	https://www.spoteron.com/constmapspots/727031	-7.359.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spoteron.com/images/spots/00003720221209/ckem9cnv-gf8k0f8m84kpc5suw5k.jpg	Tambaba	2022-12-09 09:52	No Obvious Change			FALSO			Tripod			Maré baixa	2022-12-09 12:59	no	
727034	https://www.spoteron.com/constmapspots/727034	-7.285.806	-34.800.568	VERDA-DEIRO	Free Roaming	https://files.spoteron.com/images/spots/00003720221209/sl4ld-dk4lkc0bz3fu5kdx60ftu.jpg	prua de jacuã	2022-12-09 10:23	No Obvious Change			FALSO				160		Maré baixa			

ID	LINK	LATITUDE	LONGITUDE	CHECKBOX LOCATION	CATEGORY	IMAGE	NAME OF LOCATION	SPOTTED AT	CHANGES LAST UP. DATE	REASON FOR CHANGE	OTHER CAUSE	ADVANCED OPTIONS	IMAGE CAPTURE TYPE	TIDE LEVEL	DIV METHOD	PHOTO HEIGHT	SPOT NAME	DESCRIPTION	CREATED AT	MODIFIED AT	DELETED
727035	727035	-7.285.806	-34.800.568	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/09/instagcbl4e9dshzvs88fngshkq1yb.jpg	Prta de jacumã (praça do mar)	2022-12-09 10:28				VERDA-DEIRO	Snapshot (Standard)	Low Tide	Tripod		Praça do mar	Maré baixa faixa de areia extensa, recifes exposto	2022-12-09 13:34		
729084	708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/16/6t9xstl1q0b-blrb6smtee7yxazsqa.jpg	Cantinho do amor	2022-12-16 09:17	Coast Has Narrowed (Erosion)	Tide, Waves, Natural Trend		VERDA-DEIRO	Snapshot (Standard)	Rising Tide	Tripod		Bar cantinho do amor		2022-12-16 12:22		
729085	708398	-7.276.242	-34.800.442	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/16/6t9xstl1q0b-blrb6smtee7yxazsqa.jpg	Cantinho do amor	2022-12-16 09:19	Coast Has Narrowed (Erosion)	Tide, Waves, Natural Trend		VERDA-DEIRO	Snapshot (Standard)	Rising Tide	Tripod		Bar cantinho do amor	Faixa de areia mais estreita presença de algas do tipo sargaca	2022-12-16 12:25		
729091	689253	-7.285.806	-34.800.568	VERDA-DEIRO	Free Roaming	https://files.spotteron.com/images/spots/000037/2022/12/16/6t9xstl1q0b-blrb6smtee7yxazsqa.jpg	prta de jacumã	2022-12-16 09:49	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	Rising Tide		160			2022-12-16 12:52		
729099	704736	-7.312.656	-34.802.545	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/16/cuqgo1v-qm75tdhvt3xw2h2p7xk81.jpg	Tabatinga 2 lado esquerdo da escada	2022-12-16 10:39	Coast Has Grown (Accretion)	Tide, Waves, Wind, Natural Trend		VERDA-DEIRO	Snapshot (Standard)	Rising Tide	Tripod			Barreira do rio se rompendo acesso direto ao mar e alegando a faixa de areia	2022-12-16 13:45		
729100	711598	-7.316.057	-34.804.397	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/16/qxdbuagz4l-d7e4m3d62wbv4s9x17zqg.jpg	Tabatinga 2	2022-12-16 10:46	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	High Tide	Tripod		Lado direito da escada		2022-12-16 13:48		
729103	711598	-7.316.057	-34.804.397	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/16/89vubdl-qx3lk1v13sm1rxx1l1qpf9b.jpg	Tabatinga 2	2022-12-16 10:47	Coast Has Grown (Accretion)	Tide, Waves, Natural Trend, Wind		VERDA-DEIRO	Snapshot (Standard)				Lado direito da escada	Faixa de areia mais extensa, presença de algas(sargaca) e recifes mais visíveis	2022-12-16 13:51	2022-12-16 15:22	
729113	704743	-7.359.341	-34.805.318	VERDA-DEIRO	Diy Station	https://files.spotteron.com/images/spots/000037/2022/12/16/7oim78d-5dbut14d0bjkxwb-fm8m.jpg	Tambaba	2022-12-16 11:17	No Obvious Change			VERDA-DEIRO	Snapshot (Standard)	High Tide	Tripod				2022-12-16 14:19		